

Facility ID#:

UST - CLOSURE INSPECTION CHECKLIST

Inspector's Name Laron K. CihabDate October 14, 1997**I. SITE INFORMATION**Facility/Site Name: NOAA National Weather ServiceCity/Town: 6425 Aircraft Parkway, GreensboroCounty: GuilfordOwner: NOAA National Weather ServicePhone: (910) 868-9269

Operator: _____

Phone: _____

Contractor: A+D EnvironmentalPhone: (910) 434-7750

Laboratory: _____

Phone: _____

Directions: _____

Date of scheduled UST Removal (from GW/UST-3): 10-14-97**II. UST STATUS**

Tank #:	1	2	3	4	5	6	7	8
Size:	500							
Product:	DIESEL							

Remark Y (YES), N (NO), NA (NOT APPLICABLE), and U (UNKNOWN) for each of the following:

III. CLOSURE PROCEDURES

U Tanks, tools, equipment bonded or grounded?
U OSHA/Safety violations observed: _____

Y Product in piping drained into tank?

NA Tanks properly purged? Method: Already < 20% LEL

Y Tanks emptied and cleaned properly? Pumped out 250 gallons (A+D)

Y Accessible openings capped or plugged except 1/8" vent?

N UST(s) closed in place and filled with solid inert material?

Final destination of tank(s): A+D Environmental

Final destination of product, contaminated soil, contaminated water, etc. _____

IV. SITE DESCRIPTION

N Soil stained and/or petroleum odor?

N Contaminated soil excavated? Quantity? (estimate): _____

NA Soil samples taken of excavated soil left on site?

Excavated soil on plastic or trucked away? (Circle one)

Tank(s) condition: Very good

Product line condition?: _____

V. SAMPLING LOCATION

N USTs < 20': one at each end? Tank on top of pad

NA USTs > 20': one at each end & middle?

Y Samples every 20' of piping?

NA Samples under each tank island?

NA Water samples? (in lieu of soil samples)

Samples: floor, side, stockpiled soil?: _____

VI SAMPLE COLLECTION QUALITY CONTROL

Collection method: (Shovel, auger, back hoe): *Gloved hand*
Y How Preserved? (ice):
NA Tools decontaminated: (soap, Di-H₂O, MEOH, organic-free H₂O).
Y Chain-of-Custody form (required):

VII SUMMARY OF SITE CONDITIONS

N Groundwater intersected?
N Bedrock encountered?
N Contaminated soil?
N Free product in excavation?

VIII SAMPLES COLLECTED BY DEM PERSONNEL

N Samples collected?
 Sample locations:

XV COMMENTS:

No fire inspector on site. 1% LEL before pulling.

DIAGRAM OF SITE INVESTIGATION AT UST CLOSURE

Diagram should include physical structures such as roads, buildings, etc.; former location of USTs, pumps, product lines; soil sampling locations; and location of excavated soil.

